Sherwood

Harsco

Sherwood GV Industrial Valve Safety Notice
3 / 4"-16 UNF Straight Thread Only w/ CGA 540, 580, 326 and BS 3 Outlets

In 2006, a design modification was made to the inlet connection on the 3 / 4"-16 UNF Straight Thread valves with CGA 540, 580, 326, and BS 3 outlet connections. Recently we have been informed certain torques applied during installation may cause a fracture at the ¾"-16 UNF valve inlet thread.

Strictly as a precautionary measure, Sherwood recommends that valves with the part numbers below marked with date codes of 05/06 (May 2006) through 06/07 (June 2007) be safely removed from service and returned for replacement.

GV(A)54051-XX(LX)-75
GV(A)32651-XX(LX)-75
GV(A)58051-XX(LX)-75
GV(A)BS351-XX(LX)-75



Only these part numbers and date codes are to be returned for replacement. Request for returns must be submitted within 90 days of this notice.

For return authorization and replacement information please contact our customer service department at 888-508-2583 or for faxes 800-416-0678.

7/19/2007