

Name: Sam Elkind

Organization: UPS

Comments: Page 18 - Shouldn't there be insulating caps on the terminals of the wet batteries? Incidents can happen (and have happened) with unprotected terminals shipped as shown.